# SENSAPHONE Monitoring Sensor

**General Accessories** 

## 10K Remote Weatherproof Temperature Sensor



#### Description

The 10K Weatherproof Remote Temperature sensor enables monitoring temperatures at a location away from a Sensaphone unit. It will measure and report the exact temperature back to the Sensaphone unit to which it is attached. The Sensaphone can be programmed to trigger an alarm when conditions exceed the set high or low temperature limits. It may be mounted anywhere air temperatures need to be measured and is suitable for use in wet, dirty environments.

### Temperature Range:

**1400, 1800, 2800, WEB600:** -87° to 168°F (-66° to 76°C)

**2000:** -90° to 200°F (-68° to 93°C) **Express II:** -80° to 200°F (-62° to 93°C) **SCADA 3000:** -35° to 205°F (-37° to 97°C)

#### Package Contents

- (1) Temperature sensor
- (1) 12' wire
- (1) Installation instructions
- (1) Mounting Hardware

#### **Specifications**

#### **Temperature Range:**

Differs depending on Sensaphone model. See above.

#### **Accuracy:**

+/- 1°F

#### **Compatibility:**

1400, 1800, 2800, 2000, Express II, SCADA 3000, and WEB600

\*Specifications subject to change without notice

10K Remote Weatherproof Temperature Sensor . . . . . . . . . FGD-0102