


ST-457 Turbo Nozzle



Repair Kit #2004571**



**** = Specify
Nozzle
Size**

ST-457

Item	Order #	Description
1	020001025	Protective cap
2	010001070	Housing Brass
3	In Repair Kit	O-ring for ceramic seat
4	In Repair Kit	O-ring for inlet
5	010001088 010001085 010001086 010001087 010001089	Inlet, complete brass 030 Inlet, complete brass 035 Inlet, complete brass 040/045 Inlet, complete brass 050/055/070 Inlet, complete brass 060/065/080/090/100
6	In Repair Kit	Ceramic Nozzle
*	2004571**	Repair Kit for Models TS-58-5 & ST-457 (Includes 1 ea. Items 3, 4, 6) ** = Specify Nozzle Size